

ACKNOWLEDGEMENT
Karnataka Lokayukta
(Under Section 7 of the Karnataka Lokayukta Act, 1984)

CASE NUMBER : **COMPT/LOK/BCD/12/2018**
District : **Bangalore (U)**

BY :

1. SUO MOTO

As per the order of Honble LOKAYUKTA, dated
on 01-01-2018

COMPLAINANT/S

AGAINST :

1. Manjunatha Prasad IAS

Commissioner, B.B.M.P., N.R. Square, Bengaluru
560002

3. H.T.Bettegowda

Chief Engineer Storm Water Drain BBMP Bangalore

✓ **4. B.G.Diwakar**

Executive Engineer East Zone BBMP Bangalore

✓ **5. H.R.Channakeshava**

Assistant Executive Engineer East Sub-
Division Storm Water Drain Bangalore

✓ **7. Basavaraju.M.**

Executive Engineer BBMP, Storm water
Drain Bangalore West Division Bengaluru.

✓ **8. Shivaprasad.H.M.**

Assistant Executive Engineer BBMP, Storm water
drain, Bangalore West Division Bengaluru.

✓ **9. Shashidar S.C.**

Assistant Executive Engineer (BBMP, Storm Water
drain Bangalore West division Bengaluru.

✓ **10. Indrani.K.M.**

Assistant Executive Engineer BBMP, Storm water
drain Bengaluru West Division Bangalore

✓ **11. B.L.Nagaraj**

Assistant Executive Engineer BBMP, Storm water
drain Bengaluru South Division Bangalore

12. Abdul Vahab.K.

Assistant Executive Engineer BBMP, Storm water
drain Bengaluru.

✓ **13. Mahadesh.H.S.**

Executive Engineer BBMP, Storm water drain,
Bommanahalli Division Bengaluru.

✓ **14. Vinay Kumar.V**

Assistant Executive Engineer BBMP, Storm water
drain Bengaluru.

Assistant Executive Engineer BBMP, Strom water drain, bommanahalli DivisionBengaluru.

16. Lokesh.J.N.

Executive Engineer BBMP, Strom water drain, KoramangalaBengaluru.

17. Prakash.H.

Assistant Executive Engineer BBMP, Strom water drainKoramangala DivisionBengaluru.

18. Renuka Swadi

Assistant Executive Engineer BBMP, Strom water drainKoramangala DivisionBengaluru.

19. M.Krishnamurthy

Executive Engineer BBMP, Strom water drainRajarajeshwari DivisionBengaluru.

20. K.V.Prakash

Assistant Executive Engineer BBMP, Strom water drainR.R.Nagar DivisonBengaluru.

21. Suryanarayana.D.S

Assistant Executive Engineer BBMP, Strom water drainR.R.NagarBengaluru.

22. S.K.Prakash

Executive Engineer BBMP, Strom water drainYelahanka DivisionBengaluru.

23. Mohan.D.S.

Assistant Executive Engineer BBMP, Strom water drainYelahanka DivisionBengaluru.

24. Rajanikanth Malli

SAssistant Executive Engineer BBMP, Strom water drainYelahankaBengaluru.

25. Malathi.R

Executive Engineer BBMP, Strom water drainMahadevapura Division Bengaluru.

27. K.Pandurangaiah

Assistant Executive Engineer BBMP, Mahadevapura Division Strom water drainBengaluru.

28. Mallikarjun.G

Assistant Executive Engineer BBMP, Strom water drainBengaluru.

29. Shivakumar.S.

Executive Engineer BBMP, Strom water drainDasarahalli DivisionBengaluru.

30. Rahul.S.b

Assistant Executive Engineer BBMP, Strom water drainDasarahalli DivisionBengaluru.

31. Harish.Y.L.

32. Assistant Executive Engineer
BBMPSouth DivisionBangalore

✓ 33. Executive Engineer
BBMPYelahnaka DivisionBangalore

✓ 34. S.T.Basavarajappa
Assistant Executive EngineerEast
DivisionBBMPBangalore

RESPONDENT/S

Allegation/Grievance
Brief : Dereliction of duty

Received From : SUO MOTO

Received On : 02-01-2018

Complaint stands
allotted to : ARE-1

Phone Number : 080-22257013 Extn - 322

CASE NUMBER : **COMPT/LOK/BCD/12/2018**

District : **Bangalore (U)**

BY :

1. SUO MOTO

As per the order of Honble LOKAYUKTA, dated
on 01-01-2018

Mobile/Landline: 00000000000

COMPLAINANT/S

AGAINST :

1. Manjunatha Prasad IAS

Commissioner, B.B.M.P., N.R. Square, Bengaluru
560002

2. Venkatesh M.R.

Engineer-in-Chief, Head Office, Annexure-I
Building, 1st Floor, N.R. Square, BBMP., Bengaluru
560001

3. Mahendra Jain IAS

Incharge Managing Director, Bengaluru Metro Rail
Corporation Ltd., 3rd Floor, BMTC Complex, K.H.
Road, Shanthinagar, Bengaluru
560027

4. Somashekar S

Chief Engineer (Road Infrastructure), Head Office
Annexure-3 Building, 3rd Floor, BBMP, Bengaluru.

5. Prahalad B.S.

Superintending Engineer (Road Infrastructure),
Head Office Annexure-3 Building, 3rd Floor,
BBMP, Bengaluru.

6. Shivaprakash

Executive Engineer (Road Infrastructure - East),
Head Office Annexure-3 Building, 3rd Floor,
BBMP, Bengaluru.

7. Malathesh

Executive Engineer (Road Infrastructure - West),
Head Office Annexure-3 Building, 3rd Floor,
BBMP, Bengaluru.

8. Dharanendra Kumar

Executive Engineer (Road Infrastructure - South),
Head Office Annexure-3 Building, 3rd Floor,
BBMP, Bengaluru.

9. Nandish

Executive Engineer (Road Infrastructure -
R.R.Nagara), BBMP, Bengaluru.

10. Mukunda

Executive Engineer (Road Infrastructure -
Yelahanka), BBMP, Bengaluru.

Mahadevapura), BBMP, Bengaluru.

12. Muralidhar

Executive Engineer (Road Infrastructure - Dasarahalli), BBMP, Bengaluru.

13. Basavaraj

Executive Engineer (Road Infrastructure - Bommanahalli), BBMP, Bengaluru.

14. Prabhakar

Executive Engineer (Road Infrastructure - Special Division), BBMP, Bengaluru.

15. Praveen Lingaiah

Executive Engineer (Road Infrastructure - Road Widening), BBMP, Bengaluru.

16. Nagaraj K.T.

Chief Engineer (Project - Central), Head Office, Annexure-3 Building, 3rd Floor, BBMP, Bengaluru.

17. Ramesh

Superintending Engineer (Project - Central), Head Office, Annexure-3 Building, 3rd Floor, BBMP, Bengaluru.

18. Basavaraj R Kabade

Executive Engineer (Project Central -V), Head Office, Annexure-3 Building, 3rd Floor, BBMP, Bengaluru.

19. Ramachandra

Executive Engineer (Project Central -I), Head Office, Annexure-3 Building, 3rd Floor, BBMP, Bengaluru.

20. Ramesh

Executive Engineer (Project Central -II), Head Office, Annexure-3 Building, 3rd Floor, BBMP, Bengaluru.

21. Narashima Shastri

Executive Engineer (Project Central -III), Head Office, Annexure-3 Building, 3rd Floor, BBMP, Bengaluru.

22. Lokesh

Executive Engineer (Project Central -IV), Head Office, Annexure-3 Building, 3rd Floor, BBMP, Bengaluru.

23. Govindaraju R.V.

Chief Engineer (West), BBMP Office, Ground Floor, Sampige Road, Bashyam Park, Seshadripuram, Bengaluru.
560020

24. Nagaraju S.D.

Superintending Engineer (West), BBMP Office, Ground Floor, Sampige Road, Bashyam Park, Seshadripuram, Bengaluru.
560020

Sampige Road, Seshadripuram, Bengaluru.

26. Thimmarasu

Executive Engineer (Mahalakshmpuram), BBMP
Bengaluru.

27. Shashikumar

Executive Engineer (Rajajinagara), BBMP Office,
Bengaluru.

28. Palaksha

Executive Engineer (Gandhinagar), BBMP Office,
Bengaluru.

29. Tanveer Ahmad

Executive Engineer (Chamarajapet), BBMP Office,
Bengaluru.

30. Srikantagowda

Executive Engineer - (Govindarajanagar), BBMP
Office, Bengaluru.

31. Prabhakar

Chief Engineer (South),BBMP Complelx, 9th
Main,Jayanagar 2nd Block, BBMP,Bengaluru
560011

32. Narasaram Rao

Superintending Engineer (South),BBMP Complelx,
9th Main,Jayanagar 2nd Block, BBMP,Bengaluru

33. Bhimesh H.

Executive Engineer (Vijayanagara),BBMP
Complelx, 9th Main,Jayanagar 2nd Block,
BBMP,Bengaluru

34. Dharanendra Kumar

Executive Engineer (Basavanagudi),BBMP
Complelx, 9th Main,Jayanagar 2nd Block,
BBMP,Bengaluru

35. Vijayakumar Haridas

Executive Engineer (Padmanabhanagara),BBMP
Complelx, 9th Main,Jayanagar 2nd Block,
BBMP,Bengaluru

36. Srinivasa Reddy

Executive Engineer (B.T.M. Layout), BBMP
Complelx, 9th Main, Jayanagar 2nd Block, BBMP,
Bengaluru.

37. Vishwanatha J.

Executive Engineer (Jayanagar),BBMP Complelx,
9th Main,Jayanagar 2nd Block, BBMP,Bengaluru

38. Manjunath Reddy

Executive Engineer (Chickpet),BBMP Complelx,
9th Main,Jayanagar 2nd Block, BBMP,Bengaluru

39. Prasad B.S.

Chief Engineer (East), P.U. Building,Mayohall,
18th Floor, M.G. Road, BBMP, Bengaluru
560001

Building, Mayohall, 18th Floor, M.G. Road, BBMP,
Bengaluru

41. Nagaraj R.

Executive Engineer (Shantinagara), P.U. Building,
Mayohall, 18th Floor, M.G. Road, BBMP,
Bengaluru

42. Maradi Rangappa

Executive Engineer (Shivajinagar) P.U. Building,
Mayohall, 18th Floor, M.G. Road, BBMP,
Bengaluru

43. Amruthkumar Solanki

Executive Engineer (C.V.Raman Nagara)P.U.
Building, Mayohall, 18th Floor, M.G. Road,
BBMP, Bengaluru

44. Neelakantaiah

Incharge Executive Engineer Pulakeshinagara),
P.U. Building, Mayohall, 18th Floor, M.G. Road,
BBMP, Bengaluru

45. Mohangowda

Executive Engineer(Sarvagnanagara) P.U. Building,
Mayohall, 18th Floor, M.G. Road, BBMP,
Bengaluru

46. Mohan Hondadakere

Executive Engineer (Hebbal)P.U. Building,
Mayohall, 18th Floor, M.G. Road, BBMP,
Bengaluru

47. Parameshwaraiiah

Chief Engineer (Yelahanka)Amruthahalli Cross,
Bellary Road,Byatarayanapura, BBMP, Bengaluru
560092

48. Vasu

Incharge Superintending Engineer (Yelahanka),
Amruthahalli Cross, Bellary Road,
Byatarayanapura, BBMP, Bengaluru
560092

49. Vasu

Executive Engineer (Yelahanka)Amruthahalli
Cross, Bellary Road,Byatarayanapura, BBMP,
Bengaluru
560092

50. Mohan Das

Executive Engineer
(Byatarayanapura)Amruthahalli Cross, Bellary
Road,Byatarayanapura, BBMP, Bengaluru
560092

51. Govindaraj R.V.

Incharge Chief Engineer (R.R. Nagara), Ideal
Homes, RR Nagar, BBMP, Bengaluru
560098

52. Umashankar

560098

53. Srinivas

Executive Engineer (R.R. Nagara), Ideal Homes,
RR Nagar, BBMP, Bengaluru

560098

54. Lokesh

Executive Engineer (Kengeri), Ideal Homes, RR
Nagar, BBMP, Bengaluru

560098

55. Vijayakumar

Incharge Chief Engineer (Dasarahalli)Hesaragatta
Road, Bagalgunte MET Layout, BBMP, Bengaluru

560073

56. Vijayakumar

Incharge Superintending Engineer (Dasarahalli),
Ideal Homes, RR Nagar, BBMP, Bengaluru

560073

57. Sheshadri

Executive Engineer (Dasarahalli), Ideal Homes, RR
Nagar, BBMP, Bengaluru

560073

58. Nataraj

Incharge Chief Engineer (Mahadevapura), BBMP
Complex, RHB Colony, Whitefield RIADM,
BBMP, Bengaluru

560048

59. Nataraj

Superintending Engineer (Mahadevapura), BBMP
Complex, RHB Colony, Whitefield RIADM,
BBMP, Bengaluru

560048

60. Ranganath

Executive Engineer (K.R.Puram), BBMP Complex,
RHB Colony, Whitefield RIADM, BBMP,
Bengaluru

560048

61. Dayanand

Executive Engineer (Mahadevapura), BBMP
Complex, RHB Colony, Whitefield RIADM,
BBMP, Bengaluru

560048

62. Siddegowda K.

Chief Engineer (Bommanahalli), BBMP Complex,
Begur Main Road, Bommanahalli, BBMP,
Bengaluru

560068

63. Suguna

Superintending Engineer (Bommanahalli), BBMP
Complex, RHB Colony, Whitefield RIADM,
BBMP, Bengaluru

560068

Complex, RHB Colony, Whitefield RIADM,
BBMP, Bengaluru
560068

65. Nishar Ahmed Khan

Executive Engineer (Bengaluru South), BBMP
Complex, RHB Colony, Whitefield RIADM,
BBMP, Bengaluru
560068

66. Rajendra Cholan P, IAS

Managing Director, Bengaluru Electricity Supply
Company Ltd., Corporate Office, K.R. Circle,
Bengaluru.
560001

67. Tushar Girinath, IAS

Chairman, BWSSB, Cauvery Bhavan, K.G. Road,
Bengaluru
560009

68) Chief Engineer
BWSSB, Cauvery
Bhavan, Bengaluru
69) Chief Engineer
BESCOM (CG.M)
Bengaluru

RESPONDENT/S

Allegation/Grievance
Brief : Dereliction of duty

Received From : SUO MOTO

Received On : 02-01-2018

B. G. S. 2/18
Seal and Signature

Complaint stands
allotted to : ARE-1

SCRUTINY AND OPINION

- 1 - BCD - 12/2018

KARNATAKA LOKAYUKTA : BENGALURU

Date: 01-01-2018

ORDER

'The Hindu' - daily newspaper dated 16-12-2017 has published a news item highlighting the digging of the road/open drain which would result in risk to the life of the students.

2. It is useful to extract the said news item which reads as hereunder:

"Nearly a month after a portion of the 3rd Cross Road at NGEF Layout in Kasturi Nagar (next to Presidency School) was dug up for repair work related to the storm-water drain, hundreds of children have been forced to walk to the school in the little available space on the road.

The road, which many of the school buses use, is blocked to vehicular traffic with debris from the dug up portion lying about in mounds.

G.Thangadurai, Director, Presidency Group of Schools, said that he was worried about the safety of his students. "The place has been dug up and the debris dumped on the road leaving very little space for students

BCD-12/2018

- 2 -

to walk. Also, there is no fencing around the work site and it is risky to walk. The drain has been left open," he said.

Stating that no work has been going on for many days now, Mr.Thangadurai said the BBMP should have given priority to this work considering it is being taken up right next to a school. "We tried reaching out to BBMP officials, but got no response. We were neither given prior notice nor have been told how long the work would take to complete," he said.

Shreekesh S, a Class 7 student, who cycles to school every day, said he has to be extra cautious as there are loose stone everywhere. "If a bike comes from the opposite direction, I have to ride on the rubble. It is very risky and dangerous, and my parents are worried," he said.

Meenakshi, Councillor of Ward No. 50, where the school is located, said there were some damage to the drain and repair work has been taken up. According to Chennakesava, Bruhat Bengaluru Mahanagara Palike Assistant Executive Engineer, SWD, the repair was badly needed.

"The drain was old and there were lot of damages. We are building a concrete drain. The curing process takes 15 days.....so we were unable to start work. It will start within two days and completed before the end of the month," he said".



3. The news item extracted above, indicates that the life of the members of the public and more particularly students life is exposed to serious risk and jeopardy. No doubt, the digging up of the road and open drain has drawn the attention of the Councillor of the Ward No.50 and Assistant Executive Engineer of BBMP, SWD. However, if the digging up of the road and open drain is not immediately attended to and if no steps are taken to protect the life of the members of the public and more particularly young students/children, it will result in serious injury to the life of the public and their safety.

4. The experience and the information received by me from various sources indicate that similar situation exists in other parts of Bengaluru City, which is highlighted in the news item referred to above. It is needless to point out that the BBMP and the concerned authorities like, BWSSB, BESCOM and BMRCL have an obligation when they are entrusted with the work which they are required to do, they are required to execute the work without undue delay and dig up the roads, if the



BUD-12/2018

4

roads are required to be dug up and they are immediately required to be filled up and sufficient precautions are to be taken not to expose the members of the public to any risk and similar steps will also be required to be taken in respect of the open drains.

5. Therefore, in the light of what is stated above, I am of the view, it is in larger public interest to institute suo-motu proceedings in exercise of the power conferred on me under Section 7(1) and 9 (3)(a) of the Karnataka Lokayukta Act, 1984. Accordingly, it is ordered. The office is directed to register this proceeding as suo-motu proceedings.

6. For the purpose of adjudication of the matter at issue, which is highlighted in the news item referred to above, it is necessary to issue notice to the following officers/officials:


- (1) Sri. N.Manjunatha Prasad, IAS,
Commissioner, BBMP,
N.R.Square, Bengaluru - 560 002.
- (2) Sri. M.R.Venkatesh,
Engineer-in-Chief,



-5- BCD - 12/18

Head Office, Annexure-1 Building,
1st Floor, N.R.Square,
BBMP, Bengaluru - 560 001.

Road Infrastructure

- (3) Sri. Mahendra Jain, IAS,
I/c Managing Director,
Bengaluru Metro Rail Corporation Ltd.,
3rd Floor, BMTC Complex, K.H.Road,
Shanthinagar, Bengaluru - 560 027.
- (4) Sri. S. Somashekar,
Chief Engineer (Road Infrastructure)
Head Office Annexure-3 Building
3rd Floor, BBMP, Bengaluru.
- 4A Sri. B.S. Prahalad,
Superintending Engineer (Road Infrastructure)
- 4B Sri. Shivaprakash,
Executive Engineer (Road Infrastructure - East)
- 4C Sri. Malathesh,
Executive Engineer (Road Infrastructure - West)
- 4D Sri. Dharanendra Kumar,
Executive Engineer (Road Infrastructure - South)
- 4E Sri. Nandish,
Executive Engineer (Road Infrastructure - R R
Nagara)
- 4F Sri. Mukunda,
Executive Engineer (Road Infrastructure - Yelahanka)
- 4G Sri. Jayashankara Reddy,
Executive Engineer (Road Infrastructure -
Mahadevapura)
- 

- 4H Sri. Muralidhar,
Executive Engineer (Road Infrastructure –
Dasarahalli) ,
- 4I Sri. Basavaraj,
Executive Engineer (Road Infrastructure –
Bommanahalli) ,
- 4J Sri. Prabhakar,
Executive Engineer (Road Infrastructure –
Special Division) ,
- 4K Sri. Praveen Lingaiah,
Executive Engineer (Road Widening) ,

Project Central

- (5) Sri. K.T.Nagaraj,
Chief Engineer (Project – Central)
Head Office Annexure-3 Building
3rd Floor, BBMP, Bengaluru ,
- 5A Sri. Ramesh,
Superintending Engineer (Project Central) ,
- 5B Sri. Basavaraj R Kabade,
Executive Engineer (Project Central - V) ,
- 5C Sri. Ramachandra,
Executive Engineer (Project Central - I) ,
- 5D Sri. Ramesh,
Executive Engineer (Project Central - II) ,
- 5E Sri. Narashima Shastri,
Executive Engineer (Project Central - III) ,
- 5F Sri. Lokesh,
Executive Engineer (Project Central - IV) ,



West Zone

- (6) Sri R.V. Govindaraju,
Chief Engineer (West),
BBMP Office, Ground Floor,
Sampige Road, Bashyam Park, Seshadripuram,
Bengaluru - 560 020. ✓
- 6A Sri. S.D.Nagaraju,
Superintending Engineer (West) ✓
- 6B Sri. Narayana,
Executive Engineer (Malleswaram) ✓
- 6C Sri. Thimmarasu,
Executive Engineer (Mahalakshmpuram) ✓
- 6D Sri. Shashikumar,
Executive Engineer (Rajajinagara) ✓
- 6E Sri. Palaksha,
Executive Engineer (Gandhinagar) ✓
- 6F Sri. Tanveer Ahmad,
Executive Engineer (Chamarajapet) ✓
- 6G Sri. Srikantagowda ,
Executive Engineer (Govindarajanagar) ✓

South Zone

- (7) Sri. Prabhakar,
Chief Engineer (South)
BBMP Complex, 9th Main,
Jayanagar 2nd Block, BBMP, Bengaluru - 560 011 ✓
- 7A Sri. Narasaram Rao,
Superintending Engineer (South) ✓ Rao
- 7B Sri. H. Bhimesh,
Executive Engineer (Vijayanagara) ✓

BU-12/2018

- 7C Sri. Dharanendra Kumar,
Executive Engineer (Basavanagudi) ¶
- 7D Sri. Vijayakumar Haridas,
Executive Engineer (Padmanabhanagara) ¶
- 7E Sri. Srinivasa Reddy,
Executive Engineer (B.T.M. Layout) ¶
- 7F Sri. J.Vishwanatha,
Executive Engineer (Jayanagar) ¶
- 7G Sri. Manjunath Reddy,
Executive Engineer (Chickpet) ¶

East Zone

- (8) Sri. B.S. Prasad
Chief Engineer (East), P.U.Building,
Mayohall, 18th Floor, M.G.Road, BBMP,
Bengaluru - 560 001. ¶
- 8A Sri. Mohan Gowda,
I/C Superintending Engineer (East) ,
- 8B Sri. R.Nagaraj,
Executive Engineer (Shanthinagara) ¶ + 12
- 8C Sri. Maradi Rangappa,
Executive Engineer (Shivajinagar) ¶
- 8D Sri. Amruthkumar Solanki,
Executive Engineer (C.V. Raman Nagara) ¶ + 13
- 8E Sri. Neelakantiah,
I/c Executive Engineer (Pulakeshinagra) ,
- 8F Sri. Mohangowda
Executive Engineer (Sarvagnanagara) ,

8G Sri. Mohan Hondadakere,
Executive Engineer (Hebbal) ✓

Yelahanka Zone

(9) Sri. Parameswaraiyah,
Chief Engineer (Yelahanka)
Amruthahalli Cross, Bellary Road,
Byatarayanapura, BBMP, Bengaluru - 560 092. ✓

9A Sri. Vasu,
I/c Superintending Engineer (Yelahanka) ✓

9B Sri. Vasu,
Executive Engineer (Yelahanka) ✓

9C Sri. Mohan Das,
Executive Engineer (Byatarayanapura) ✓

Raja Rajeswari Nagar Zone -

(10) Sri R.V.Govindaraj,
I/C Chief Engineer (R.R.Nagara)
Ideal Homes, RR Nagar, BBMP, Bengaluru - 560 098. ✓

10A Sri. Umashankar,
Superintending Engineer (R.R. Nagara) ✓

10B Sri. Srinivas,
Executive Engineer (R.R. Nagara) ✓

10C Sri. Lokesh,
Executive Engineer (Kengeri) ✓

(11) Sri Vijayakumar,
I/c Chief Engineer (Dasarahalli)
Hesaragatta Road, Bagalgunte MET Layout,
BBMP, Bengaluru - 560 073. ✓

11A Sri Vijayakumar,
I/c Superintending Engineer (Dasarahalli) ✓



11B Sri. Sheshadri,
Executive Engineer (Dasarahalli) ✓

Mahadevapura Zone

(12) Sri. Nataraj,
I/c Chief Engineer (Mahadevapura),
BBMP Complex, RHB Colony, Whitefield RIADM,
BBMP, Bengaluru - 560 048. ✓

12A Sri. Nataraj,
Superintending Engineer (Mahadevbapura) ✓

12B Sri. Ranganath,
Executive Engineer (K R Puram) ✓

12C Sri. Dayanand,
Executive Engineer (Mahadevapura) ✓

Bommanahalli Zone

(13) Sri. K. Siddegowda,
Chief Engineer (Bommanahalli),
BBMP Complex, Begur Main Road,
Bommanahalli, BBMP, Bengaluru - 560 068. ✓

13A Smt. Suguna,
Superintending Engineer (Bommanahalli) ✓

13B Sri. Chandrashekar,
Executive Engineer (Bommanahalli) ✓

13C Sri. Nishar Ahmed Khan,
Executive Engineer (Bangalore South) ✓

14. Sri. P. Rajendra Cholan, IAS.,
Managing Director, Bengaluru Electricity Supply
Company Ltd., Corporate Office, K.R.Circle,
Bengaluru-560 001. ✓

15. Sri. Tushar Girinath, IAS.,
Chairman, BWSSB, Cauvery Bhavan,
K.G.Road, Bengaluru-560 009.

7. The authorities referred to above, are directed to be impleaded as Respondents in this proceeding. The Respondents referred to above, that is each of the Chief Engineers and the concerned officers of BESCO & BWSSB, are directed to inspect the area which comes under their respective jurisdiction and submit a report with regard to the roads dug up within their jurisdiction and open drains available within their jurisdiction and steps taken by each one of them to fill up the roads which are dug up and cover the open drain and such other steps taken to protect the life of the public and protect the public interest. They shall submit the status report with reference to the matters referred to above within 10 weeks from the date of communication of this order.


8. However, in the mean while, it is needless to point out that the Respondent-1 and Chief Engineers of all



BCD-12/2018

Zones are directed to fill up the dug up road; and open drain located at 3rd Cross Road at NGEF Layout in Kasturi Nagar (next to Presidency School), without loss of time and submit an interim report with regard to the steps taken within 10 days from the date of communication of this order. Notice may also be issued to the Staff Reporter of newspaper 'The Hindu', who has reported the news item to assist the Lokayukta. The copy of the paper publication may be forwarded to the Respondents.

9. **List this case on 20-01-2018.** Only the Chief Engineer, Bruhat Bengaluru Mahanagara Palike (East), (Respondent-8) and Sri. Amruthkumar Salanki, Executive Engineer, C.V. Raman Nagar (Respondent-8D) are directed to be present on 20-01-2018 at 02-30 p.m.


(Justice P. Vishwanatha Shetty),
Lokayukta,
Karnataka State.

AS*

ARLO-4 (Compts.)

ARE-1)

O R D E R

Sri B.S.Prasad, Chief Engineer (East), BBMP, Bengaluru is present along with Sri Amruth Kumar Salanki, Executive Engineer, C.V.Raman Nagar, BBMP, Bengaluru, and filed a report dated 19.01.2018. Along with the report the Executive Engineer, C.V.Raman Nagar, BBMP, Bengaluru has produced the photographs showing the progress of the work. The same is placed on record. However, it is useful to extract the report dated 19.01.2018, which reads here as under –

“ಮಾನ್ಯರೇ

ವಿಷಯ:-ವಾರ್ಡ್ ಸಂಖ್ಯೆ:50ರ

ಕಸ್ತೂರಿನಗರದ Presidency school,
3^{ನೇ} ಕ್ರಾಸ್ ಹತ್ತಿರ ರಾಜಕಾಲುವೆ ಕಾಮಗಾರಿಗೆ
ಸಂಬಂಧಿಸಿದಂತೆ ದಿನಾಂಕ:16-12-2017 ರಂದು

“The Hindu” ದಿನ ಪತ್ರಿಕೆಯಲ್ಲಿ
ಪ್ರಕಟವಾದ ವರದಿಯನ್ನಾಧರಿಸಿ ಮಾನ್ಯ
ಲೋಕಾಯುಕ್ತ ಸಂಸ್ಥೆಯಲ್ಲಿ ದಾಖಲಾದ ಸ್ವಯಂ ಪ್ರೇರಿತ
ದೂರಿಸ ಬಗ್ಗೆ ವರದಿ.

ಉಲ್ಲೇಖ:- ಗೌರವಾನ್ವಿತ ಲೋಕಾಯುಕ್ತ ರವರ ಆದೇಶ ದಿನಾಂಕ:
01-01-2018

ಮೇಲ್ಕಂಡ ವಿಷಯಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ, ಸಿ.ವಿ.ರಾಮನಗರ ಉಪ
ವಿಭಾಗ ವ್ಯಾಪ್ತಿಯ ಕಸ್ತೂರಿನಗರ 3ನೇ ಅಡ್ಡರಸ್ತೆಯಲ್ಲಿ ಪ್ರಸಿಡೆನ್ಸಿ ಸಂಸ್ಥೆಯ ಶಾಲೆಯ



BCP-12/2018

-14-

ಪಕ್ಕದಲ್ಲಿ ಬೃಹತ್ ನೀರು ಗಾಲುವೆಯ ಕಾಮಗಾರಿಯು ಪ್ರಗತಿಯಲ್ಲಿದ್ದು, ಈ ಕಾಮಗಾರಿಯಿಂದ ಶಾಲಾ ವಿದ್ಯಾರ್ಥಿಗಳಿಗೆ ಹಾಗೂ ಸಾರ್ವಜನಿಕರಿಗೆ ಓಡಾಡಲು ತೊಂದರೆ ಆಗುತ್ತಿರುವ ಬಗ್ಗೆ ದ ಹಿಂದು ಇಂಗ್ಲಿಷ್ ದಿನ ಪತ್ರಿಕೆಯಲ್ಲಿ ದಿನಾಂಕ: 16-12-2017 ರಂದು "Dug-up road open drain put student at risk" ಎಂಬ ಲೆಕ್ಕ ಶೀರ್ಷಿಕೆಯಡಿ ಪ್ರಕಟವಾದ ವರದಿಯನ್ನು ಆಧಾರಿಸಿ ಮಾನ್ಯ ಲೋಕಾಯುಕ್ತರವರು ಸ್ವಯಂ ಪ್ರೇರಿತ ದೂರನ್ನು ದಾಖಲಿಸಿಕೊಂಡಿರುತ್ತಾರೆ.

ಕಸ್ತೂರಿನಗರ 3ನೇ ಅಡ್ಡರಸ್ತೆಯಲ್ಲಿ ಬೃಹತ್ ನೀರುಗಾಲುವೆ ಕಾಮಗಾರಿಗಾಗಿ ಅಗೆದಿರುವ ರಸ್ತೆ ಮತ್ತು ಕಾಲುವೆಗಳನ್ನು ಅತೀ ಶೀಘ್ರವಾಗಿ ಮುಚ್ಚಿಸಿ ದಿನಾಂಕ:20-01-2018ರ ಅಪರಾಹ್ನ 2.30 ಘಂಟೆಗೆ ಮುಖ್ಯ ಅಭಿಯಂತರರು(ಪೂರ್ವ) ಮತ್ತು ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು(ಸಿ.ವಿ.ರಾಮನಗರ ವಿಭಾಗ) ರವರು ಖದ್ದಾಗಿ ಹಾಜರಾಗಬೇಕೆಂದು ಗೌರವಾನ್ವಿತ ಲೋಕಾಯುಕ್ತರವರು ದಿನಾಂಕ:01-01-2018ರಂದು ಆದೇಶ ಜಾರಿ ಮಾಡಿರುತ್ತಾರೆ.

ಕಸ್ತೂರಿನಗರ 3ನೇ ಅಡ್ಡರಸ್ತೆ ಪ್ರಸಿಡೆನ್ಸಿ ಶಾಲೆಯ ಹತ್ತಿರ ಇರುವ ಬೃಹತ್ ನೀರು ಗಾಲುವೆ ದುರಸ್ತಿ ಕಾಮಗಾರಿಯು ಪಾಲಿಕೆಯ ಬೃಹತ್ ನೀರುಗಾಲುವೆ ವಿಭಾಗದವರಿಂದ ನಿರ್ವಹಿಸಲಾಗುತ್ತಿದೆ. ಹಾಗೂ ಸದರಿ ಬೃಹತ್ ನೀರುಗಾಲುವೆ ದುರಸ್ತಿ ಕಾಮಗಾರಿಯ ವಿವರವನ್ನು ಶ್ರೀ.ಚಿನ್ನಕೇಶವ, ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು, ಬೃಹತ್ ನೀರುಗಾಲುವೆ ಇವರು "The Hindu" ದಿನ ಪತ್ರಿಕೆಗೆ ಹೇಳಿಕೆ ನೀಡಿರುವುದು ಪತ್ರಿಕೆಯಲ್ಲಿ ವಿಶ್ಲೇಷಿಸಿದೆ. ಆದ್ದರಿಂದ ಮಾನ್ಯ ಲೋಕಾಯುಕ್ತ ಸಂಸ್ಥೆಯವರು ದಾಖಲಿಸಿಕೊಂಡಿರುವ ಪ್ರಕರಣದ ಬಗ್ಗೆ ಬೃಹತ್ ನೀರುಗಾಲುವೆಯ ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು, ಶ್ರೀ.ಚಿನ್ನಕೇಶವ ಇವರಿಗೆ ದೂರವಾಣಿ ಮೂಲಕ ತಿಳಿಸಲಾಗಿದೆ.

ಸುಮಾರು 100mt" ಉದ್ದದ ನೀರುಗಾಲುವೆಯ ಎರಡು ಬದಿಗೆ Cement concrete ಗೋಡೆಗಳನ್ನು ನಿರ್ಮಿಸುತ್ತಿರುವುದು ದಿನಾಂಕ:08-01-2018ರಂದು ಸ್ಥಳ ಪರಿಶೀಲನೆ ಸಮಯದಲ್ಲಿ ಕಂಡು ಬಂದಿರುತ್ತದೆ (ಛಾಯ ಚಿತ್ರ ಲಗತ್ತಿಸಿದೆ)

ಈ ಮೇಲೆ ತಿಳಿಸಿರುವಂತೆ, ಮಾನ್ಯ ಲೋಕಾಯುಕ್ತ ಸಂಸ್ಥೆಯಲ್ಲಿ ದಾಖಲಾಗಿರುವ ಪ್ರಕರಣವು ದುರಸ್ತಿಯಲ್ಲಿ ಸಂಪೂರ್ಣವಾಗಿ ಪಾಲಿಕೆಯ ಬೃಹತ್ ನೀರುಕಾಲುವೆ (SWD) ವಿಭಾಗದ ನಿರ್ವಹಣೆ (ಶ್ರೀ. ಚಿನ್ನಕೇಶವ, ಸಹಾಯಕ



ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು, ಹಾಗೂ ಶ್ರೀ. ದಿವಾಕರ ಬಿ.ಜಿ. ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು) ರವರ ವ್ಯಾಪ್ತಿಗೆ ಬರುವುದರಿಂದ ಈ ಉಪ ವಿಭಾಗದಿಂದ ಯಾವುದೇ ಲೋಪವಿಲ್ಲವೆಂಬ ವರದಿಯನ್ನು ತಮ್ಮ ಮಾಹಿತಿಗಾಗಿ ಸಲ್ಲಿಸಿದೆ. ಹಾಗೂ ಈ ಪ್ರಕರಣವನ್ನು ಇತ್ಯರ್ಥಗೊಳಿಸಲು ವಿನಂತಿಸಲಾಗಿದೆ.

ವಂದನೆಗಳೊಂದಿಗೆ,

ತಮ್ಮ ವಿಶ್ವಾಸಿ

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು(ಸಿ.ವಿ.ಆರ್)
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

2) The photographs produced expose the impending risk to the people who move about in that area. It is needless to point out if any untoward incidents takes place, not only the precious human life would be under jeopardy, but it would also result in serious consequences against the BBMP Officers for their negligence. I am sure, the concerned Officers will realize the responsibilities and take effective steps forthwith to put necessary barricade and complete the work in question without any loss of time.

3) Sri B.S.Prasad pointed out that the work in question falls under the jurisdiction of officers working in Storm Water Drain Division and the concerned Chief Engineer is one Sri Bette



Gowda. He submitted that the issues raised in this proceeding are required to be answered by the concerned Chief Engineer, Executive Engineers and Assistant Executive Engineers of Storm Water Drain. Since the issue that has arisen for consideration in this proceeding falls under the jurisdiction of the concerned Chief Engineer, Executive Engineers and Assistant Executive Engineers of Storm Water Drain, I am of the view, it is desirable that the concerned Chief Engineer, Executive Engineer and Assistant Executive Engineer of Storm Water Drain, C.V.Raman Nagar Division, BBMP, Bengaluru, are required to be made as parties to this proceeding by deleting the names of Respondents No.2 to 65.

4) Further Sri Bette Gowda, Chief Engineer, the Executive Engineer and Sri Chenna Keshava, Assistant Executive Engineer working in Storm Water Drain of C.V.Raman Nagar Division, Bengaluru are required to be impleaded as respondents, as the issue raised fall within the C.V.Raman Nagar area. In the light of what is stated above, the respondents No.2 to 65 are directed to be deleted and in their



place Sri Bette Gowda, Chief Engineer, Storm Water Drain, C.V.Raman Nagar Division; Executive Engineer, Storm Water Drain, C.V.Raman Nagar Division and Sri Chenna Keshava, Assistant Executive Engineer, Storm Water Drain, C.V.Raman Nagar Division, Bengaluru are directed to be impleaded as respondents 2 to 4.

5) The Additional Registrar of Enquiries-1, Karnataka Lokayukta, has to secure the correct names and addresses of the Officers working in Storm Water Drain of various Divisions, other than the C.V.Raman Nagar Division, BBMP, Bengaluru and after receipt of the names, Office is directed to implead them as respondents No.2 to 4 and issue notices as stated above.

6) The impleaded respondents are directed to file the Status Report with regard to the present position of the works undertaken in primary and secondary Storm Water Drains in BBMP areas. They are given three weeks' time to file the Status Report.

BUD-12/2018

- 18-

Issue notices to the respondents and communicate this Order to the concerned.

List this case on 16.2.2018 at 2.30 p.m.

P. Vishwanatha Shetty
(Justice P. Vishwanatha Shetty)
Lokayukta
State of Karnataka
20/1/2018

*vi

7) Additional Registrar of Enq.1/ARLO-4

8) 16-2-2018
A.E, AEE,
EE, C.E.
ಇವರಿಗೆ ನೋಟೀಸ್
ಇವರಿಗೆ ನೋಟೀಸ್
020 68192
D-10-2-2018
ಇವರಿಗೆ ನೋಟೀಸ್
K

ARE-1

O R D E R

Sri H.T.Bette Gowda, Chief Engineer, Storm Water Drain, BBMP, Bengaluru is present along with Sri B.G.Diwakar, Executive Engineer, East Zone and Sri H.R.Channakeshava, Assistant Executive Engineer, East Sub-division of Storm Water Drain, BBMP, Bengaluru.

2) The report dated 14.2.2018 signed by the Chief Engineer and other Engineers is placed on record. It is useful to extract the said report which reads here as under –

“ಮಾನ್ಯರೇ,

ವಿಷಯ:- ಬಿ.ಬಿ.ಎಂ.ಪಿ ವ್ಯಾಪ್ತಿಯಲ್ಲಿ ರಸ್ತೆ ಅಗೆತದಿಂದ ಸಾರ್ವಜನಿಕರಿಗೆ ಎದುರಾಗಿರುವ ಅಪಾಯದ ಬಗ್ಗೆ ದಿ ಹಿಂದು ದಿನಪತ್ರಿಕೆಯಲ್ಲಿ ಪ್ರಕಟಗೊಂಡ ವಿಷಯದನ್ವಯ ಮಾನ್ಯ ಲೋಕಾಯುಕ್ತ ಸಂಸ್ಥೆಯಲ್ಲಿ ದಾಖಲಾದ ಸ್ವಯಂ ಪ್ರೇರಿತ ದೂರಿನ ಕುರಿತು.

ಉಲ್ಲೇಖ:-ತಮ್ಮ ಕಛೇರಿ ಪತ್ರದ ಸಂಖ್ಯೆ: ನಂ ಕಂ ಲೋಕ/ಬಿಸಿಡಿ/12/2018 ಅಪರ ನಿಬಂಧಕರು ವಿಚಾರಣೆಗಳು-1, ಕರ್ನಾಟಕ ಲೋಕಾಯುಕ್ತ ಬೆಂ. ದಿ:06.022018



BW-12/2018

20-

ಮೇಲ್ಕಂಡ ವಿಷಯಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ. ಸರ್ ಶ್ರೀ ಸಿ.ವಿ.ರಾಮನ್‌ನಗರ ವ್ಯಾಪ್ತಿಯ ಕಸ್ತೂರಿನಗರ 3ನೇ ಅಡ್ಡರಸ್ತೆಯಲ್ಲಿ ಪ್ರೆಸಿಡೆನ್ಸಿ ಶಾಲೆಯ ಹತ್ತಿರ ಬೃಹತ್ ಮಳೆನೀರಿನ ಕಾಮಗಾರಿಯು ಪ್ರಗತಿಯಲ್ಲಿದ್ದು ಈ ಕಾಮಗಾರಿಯಿಂದ ಶಾಲಾ ವಿದ್ಯಾರ್ಥಿಗಳಿಗೆ ಹಾಗೂ ಸಾರ್ವಜನಿಕರಿಗೆ ಒಡಾಡಲು ತೊಂದರೆ ಆಗುತ್ತಿರುವ ಬಗ್ಗೆ ದಿ ಹಿಂದು ಇಂಗ್ಲೀಷ್ ದಿನಪತ್ರಿಕೆಯಲ್ಲಿ ದಿನಾಂಕ 16.12.2017ರಂದು "Dug up road open drain put student at risk" ಎಂಬ ಶೀರ್ಷಿಕೆಯಡಿ ಪ್ರಕಟವಾದ ವರದಿಯನ್ನು ಆಧರಿಸಿ ಮಾನ್ಯ ಲೋಕಾಯುಕ್ತರವರು ಸ್ವಯಂ ಪ್ರೇರಿತ ದೂರನ್ನು ದಾಖಲಿಸಿಕೊಂಡಿರುತ್ತಾರೆ. ಮುಂದುವರೆದು ಕಸ್ತೂರಿನಗರ 3ನೇ ಅಡ್ಡರಸ್ತೆಯಲ್ಲಿ ಬೃಹತ್ ಮಳೆನೀರುಗಾಲುವೆ ಕಾಮಗಾರಿ ಬಗ್ಗೆ ಕೈಗೊಂಡ ಕ್ರಮದ ವರದಿಯನ್ನು 3 ವಾರದೊಳಗಾಗಿ ಕಛೇರಿಗೆ ವರದಿಯನ್ನು ಸಲ್ಲಿಸಲು ಮತ್ತು 16.02.2018ರಂದು ಮುದ್ದಾಗಿ ಮಾನ್ಯ ಲೋಕಾಯುಕ್ತರ ಮುಂದೆ ಹಾಜರಾಗಲು ಉಲ್ಲೇಖಿತ ಪತ್ರದಲ್ಲಿ ಸೂಚಿಸಲಾಗಿರುತ್ತದೆ.

ಕಸ್ತೂರಿನಗರ 3ನೇ ಅಡ್ಡರಸ್ತೆಯಲ್ಲಿ ಪ್ರೆಸಿಡೆನ್ಸಿ ಶಾಲೆಯ ಹತ್ತಿರ ಬೃಹತ್ ಮಳೆನೀರುಗಾಲುವೆಯ ಸೈಜುಕಲ್ಲಿನ ತಡೆಗೋಡೆಯು ಶಿಥಿಲವಾಗಿದ್ದು ಆಗಸ್ಟ್, ಸೆಪ್ಟೆಂಬರ್ ಹಾಗೂ ಅಕ್ಟೋಬರ್ 2017ರ ಮಾಹೆಗಳಲ್ಲಿ ಬಿದ್ದಂತಹ ಮಹಾಮಳೆಯಿಂದ ರಸ್ತೆಯ ಕಡೆಯ ತಡೆಗೋಡೆಯು ಸಂಪೂರ್ಣವಾಗಿ ಕುಸಿದು ಬಿದ್ದು ಅಪಾಯಕಾರಿ ಸ್ಥಿತಿಯಲ್ಲಿದ್ದುದರಿಂದ ಸದರಿ ಚರಂಡಿಯನ್ನು 35.00ಮೀ ಉದ್ದ 3.00ಮೀ ಅಗಲ ಮತ್ತು 3.40ಮೀ ಎತ್ತರಕ್ಕೆ ಆರ್.ಸಿ.ಸಿ 'ಯು' ಮಾದರಿಯ ಚರಂಡಿ ನಿರ್ಮಿಸುವುದರ ಮೂಲಕ ಶಾಶ್ವತವಾಗಿ ಸಮಸ್ಯೆ ಬಗೆಹರಿಸಲು ಮುಂದಾಗಿ, ಇದರ ಪ್ರಯುಕ್ತ ತಳಪಾಯಕ್ಕಾಗಿ ಮಣ್ಣು ಅಗೆತ ಮಾಡಿ



ಚರಂಡಿಗೆ ಹೊಂದಿಕೊಂಡಿರುವ ಅಡ್ಡ ರಸ್ತೆಯಲ್ಲಿ ಚರಂಡಿಯ ಉದ್ದಕ್ಕೂ ಎತ್ತರಕ್ಕೆ ಸುರಕ್ಷತಾ ದೃಷ್ಟಿಯಿಂದ ಅಗೆದ ಮಣ್ಣನ್ನು ಶೇಖರಿಸಿ ಸಾರ್ವಜನಿಕರು ಮತ್ತು ವಾಹನ ಸಂಚಾರವನ್ನು ನಿರ್ಬಂಧಿಸಲಾಯಿತು.

ಹಂತ ಹಂತವಾಗಿ 35.00ಮೀ ಉದ್ದದ ಮಳೆನೀರುಗಾಲುವೆಯ ತಡೆಗೋಡೆಯನ್ನು ರಸ್ತೆಯ ಮಟ್ಟಕ್ಕೆ ನಿರ್ಮಿಸಿ, ತಡೆಗೋಡೆಯ ಪಕ್ಕದಲ್ಲಿ ಶೇಖರಿಸಲಾಗಿದ್ದ ಅಗೆತದ ಮಣ್ಣಿನ ಬಹುಪಾಲನ್ನು Refilling ಮಾಡಲಾಯಿತು. ಉಳಿದ ಮಣ್ಣನ್ನು ರಸ್ತೆಯಿಂದ ತೆಗೆದು ದೂರ ಸಾಗಿಸಲಾಯಿತು. ಈಗ ರಸ್ತೆಯ ಮಟ್ಟದಿಂದ 1.00ಮೀ ಎತ್ತರಕ್ಕೆ ಎರಡು ಬದಿಗಳಲ್ಲಿ ಆರ್.ಸಿ.ಸಿ ತಡೆಗೋಡೆಯನ್ನು ನಿರ್ಮಿಸುವ ಕಾಮಗಾರಿಯು ಪ್ರಗತಿಯಲ್ಲಿರುತ್ತದೆ. ನಂತರ ಈ ಬೃಹತ್ ಮಳೆನೀರುಗಾಲುವೆಗೆ ಸಾರ್ವಜನಿಕರು ಕಸ ಎಸೆಯುವುದನ್ನು ತಡೆಯಲು ಹಾಗೂ ಈ ಭಾಗದ ನೈರ್ಮಲ್ಯವನ್ನು ಕಾಪಾಡಲು ಮತ್ತು ಸಾರ್ವಜನಿಕ ಸುರಕ್ಷತಾ ದೃಷ್ಟಿಯಿಂದ ಮಳೆನೀರುಗಾಲುವೆಯನ್ನು ಚೈನ್‌ಲಿಂಕ್‌ನಿಂದ ಕವರ್ ಮಾಡಲಾಗುವುದು. ಮುಂದುವರೆದು 2 ವಾರದಲ್ಲಿ ಕಾಮಗಾರಿಯು ಸಂಪೂರ್ಣವಾಗಿ ಪೂರ್ಣಗೊಳಿಸಲಾಗುವುದು ಎಂಬ ಅಂಶವನ್ನು ತಮ್ಮ ಅವಗಾಹನೆಗೆ ತರಲಾಗುತ್ತಿದೆ.

ಕರ್ನಾಟಕ ಘನ ಸರ್ಕಾರವು 2016-17, 2017-18ನೇ ಸಾಲಿನ ನಗರೋತ್ಥಾನ ಅನುದಾನದ ಕ್ರಿಯಾ ಯೋಜನೆಯಡಿ ರೂ.1100 ಕೋಟಿಗಳ ಅನುದಾನ ನೀಡಿದ್ದು, ಈ ಅನುದಾನದಡಿ ಬಿ.ಬಿ.ಎಂ.ಪಿ ವ್ಯಾಪ್ತಿಯ ಪ್ರಥಮ ಹಂತ ಮತ್ತು ದ್ವಿತೀಯ ಹಂತದ ಕಾಲುವೆಗಳಲ್ಲಿ ಒಟ್ಟು 192 ಕಿ.ಮೀ ಉದ್ದದ ಕಾಲುವೆ ನಿರ್ಮಾಣ / ಪುನರ್ ನಿರ್ಮಾಣ ಕಾಮಗಾರಿಗಳನ್ನು ಟೆಂಡರ್ ಮೂಲಕ ಕೈಗೊಳ್ಳಲಾಗುತ್ತಿದೆ. ವಿವರಗಳನ್ನು



ಬು- 12/2018 - 22-

(Status Report) ಲಗತ್ತಿಸಿದೆ. 2017 ಆಗಸ್ಟ್ ಮಾಹೆಯಿಂದ ಅಕ್ಟೋಬರ್ ಮಾಹೆಯವರೆಗೆ ಬಿದ್ದ ಬಾರಿ ಮಳೆಯಲ್ಲಿ ಉಂಟಾದ ಪ್ರವಾಹ ಪೀಡಿತ ಪ್ರದೇಶಗಳಲ್ಲಿ ಮಳೆನೀರುಕಾಲುವೆಗಳನ್ನು ಅಭಿವೃದ್ಧಿ ಪಡಿಸಲು ಕರ್ನಾಟಕ ಸರ್ಕಾರವು ರೂ.117.00ಕೋಟಿಗಳ ಹೆಚ್ಚುವರಿ ಅನುದಾನ ನೀಡಿದ್ದು 20 ಕಿ.ಮೀ ಉದ್ದದ ಪ್ರಥಮ / ದ್ವಿತೀಯ ಹಂತದ ಕಾಲುವೆಗಳನ್ನು ಅಭಿವೃದ್ಧಿ ಪಡಿಸಲು ಕಾಮಗಾರಿಗಳಿಗೆ ಟೆಂಡರ್ ಕರೆದಿದ್ದು, ಟೆಂಡರ್ ಪ್ರಕ್ರಿಯೆ ಪ್ರಗತಿಯಲ್ಲಿರುತ್ತದೆ. (ಕಾಮಗಾರಿಗಳ ಪ್ರಗತಿಯ ವರದಿಯನ್ನು ಲಗತ್ತಿಸಿದೆ)

ಸಹಿ/-

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು,
ಬೃಹತ್ ಮಳೆ ನೀರುಗಾಲುವೆಗಳು ಪೂರ್ವ ಉಪ ವಿಭಾಗ

ಸಹಿ/-

ಸಹಾಯಕ ಅಭಿಯಂತರರು

ಸಹಿ/-

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು,
ಬೃಹತ್ ಮಳೆ ನೀರುಗಾಲುವೆಗಳು
ಪೂರ್ವ ವಿಭಾಗ

ಸಹಿ/-


ಮುಖ್ಯ ಅಭಿಯಂತರರು,
ಬೃಹತ್ ಮಳೆ ನೀರುಗಾಲುವೆಗಳು

3) Along with the report the status of entire work taken up by the Storm Water Drain Division, BBMP, Bengaluru has been filed. The latest photographs showing the progress of the work relating to the Storm Water Drain near Presidency School at Kasturinagara Division has also been filed, and the same is placed on record. Sri H.T.Bette Gowda, Chief Engineer and



other Engineers referred to above of Storm Water Drain Division, BBMP, Bengaluru, submitted that by tomorrow the entire construction work of retaining wall of the above work will be completed and within about a week's time, chain link fencing also will be done, thereby showing the completion of the work. They also submitted once the entire work as stated above, is completed, there is no apprehension about the injury to any of members of the public including the students. The said statement made by Sri H.T.Bette Gowda, Chief Engineer and other Engineers referred to above are placed on record.

4) I have been informed by the Additional Registrar of Enquiries-1, KLA, Bengaluru that since the addresses of the concerned Engineers who are in charge of Storm Water Drain of BBMP limits, Bengaluru other than the one referred to above, could not be collected, the notices to them could not be issued. Sri H.T.Bette Gowda, Chief Engineer of Storm Water Drain, BBMP, Bengaluru submitted that he will furnish the list of all the jurisdictional Executive Engineers and Assistant Executive Engineers who are in charge of Storm Water Drain of BBMP



BCD - 12/2018

24-

limits, within 3 days to Additional Registrar of Enquiries-1. The said statement is placed on record.

- 5) On filing of the list of the Engineers referred to above, the said Engineers are directed to be impleaded as respondents and notices may be issued to them calling for their comments/reply with regard to the status of work relating to Storm Water Drain within their jurisdiction. Such Status Report shall be submitted within eight weeks' from the date of receipt of the notice.
- 6) It is needless to point out that in the mean while the concerned Engineers are required to carry out the work without any loss of time, keeping in mind the interest of public and anticipated injury that may be caused to the members of the public, if the pending work is not attended to immediately.
- 7) The presence of all the Engineers except the Chief Engineer Sri H.T.Bette Gowd is dispensed with, on the next date of hearing.



- 8) It is desirable that by the next date of hearing Sri H.T.Bette Gowda, Chief Engineer, should visit all the work spot relating to Storm Water Drain of BBMP, Bengaluru and submit his report.

List this case on **24th May 2018 at 2.30 p.m.**

P. Vishwanatha Shetty
 (Justice P. Vishwanatha Shetty)
 Lokayukta
 State of Karnataka
 16/4/2018.

*VI

- 9) Additional Registrar of Enq.1

10) 24/05/2018.

ARE-1.

ಗೌ. ಲೋಕಾಯುಕ್ತರ
 ಆದೇಶದಂತೆ ನೋಟಿಸ್
 ಜಾರಿ ಮಾಡಿದ್ದು,

ಸಿಕ್ಕಿ ಕೃತಿ ಮಾಡಿಸಿದ್ದು: R8, R9, R10
 R4, R5, R34.
 R21, R7, R11, R13, R14, R19, R25.
 R27, R20, R30, R29 & R33 ರವರೊಂದಿಗೆ
 ವರದಿ ಬಂದಿರುತ್ತದೆ.

೨.

Issue fresh
 notice to appear
 before Hon'ble Lokayukta
 on 23/8/18

25/5

11) 23/08/2018.

ARE-1

ಗೌ. ಲೋಕಾಯುಕ್ತರವರ

ಅಧೀನದಂತೆ ದೂರುದಾ-

- ರರು & ಎದುರುದಾರರಿಗೆ

ಸೋಷಲ್ ಜಾತಿ ಮಾಡಲಾ-

- ಗಿರುತ್ತದೆ & ಸ್ವೀಕೃತಿ

ಮಂಡಿಸಿದೆ.

೨.

KARNATAKA LOKAYUKTA, BENGALURU

No. Compt/Lok/BCD-12/2018

Date: 23.08.2018

ORDER

This is a suo-motu proceedings.

Sri. Bettgowda, Chief Engineer, Storm Water Drain is present along with Sri. B.G. Diwakar, Executive Engineer, Storm Water Drain, East Division and Sri. Channakeshava H.R., Assistant Executive Engineer, Storm Water Drain.

Sri. Bettgowda, Chief Engineer, Storm Water Drain has submitted a report dated; 21.08.2018. Along with the report 3 photographs have also been produced showing the work carried out to put up a RCC U-Shaped Drain in the place of damaged Kachha drain. It is useful to extract the said report, which reads as hereunder;

“ಮೇಲ್ಕಂಡ ವಿಷಯಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ, ನರ್ ಶ್ರೀ
ನಿ.ವಿ. ರಾಮನಗರ ವ್ಯಾಪ್ತಿಯ ಕಸ್ತೂರಿ ನಗರ 3ನೇ ಅಡ್ಡ
ರಸ್ತೆಯಲ್ಲಿ ಪ್ರಸಿದ್ಧಿ ಶಾಲೆಯ ಹತ್ತಿರ ಭೂಹತ್ ಮಳೆ ನೀರಿನ
ಕಾಮಗಾರಿಯು ಪ್ರಗತಿಯಲ್ಲಿದ್ದು, ಈ ಕಾಮಗಾರಿಯಿಂದ ಶಾಲಾ



ವಿದ್ಯಾರ್ಥಿಗಳಿಗೆ ಹಾಗೂ ಸಾರ್ವಜನಿಕರಿಗೆ ಓಡಾಡಲು ತೊಂದರೆ ಆಗುತ್ತಿರುವ ಬಗ್ಗೆ ದಿ ಹಿಂದು ಇನ್ಫೋರ್ಷ್ ವಿನಪತ್ರಿಕೆಯಲ್ಲಿ ದಿನಾಂಕ: 16.12.2017ರಂದು 'Dug up road open drain put student at risk' ಎಂಬ ಶೀರ್ಷಿಕೆಯಡಿ ಪ್ರಕಟವಾದ ವರದಿಯನ್ನು ಆಧರಿಸಿ ಮಾನ್ಯ ಲೋಕಾಯುಕ್ತರವರು ಸ್ವಯಂ ಪ್ರೇರಿತ ದೂರನ್ನು ದಾಖಲಿಸಿಕೊಂಡಿರುತ್ತಾರೆ.

ಉಲ್ಲೇಖ (2)ರ ಕಛೇರಿ ಪತ್ರದಲ್ಲಿ ವರದಿಯನ್ನು ಸಲ್ಲಿಸಿ ಕಾಮಗಾರಿಯ ಪ್ರಗತಿಯನ್ನು ವಿವರಿಸಲಾಗಿತ್ತು. ಮುಂದುವರೆದಂತೆ ಸದರಿ ಮೇಳನೀರುಗಾಲುವೆಯ ಆರ್.ಸಿ.ಸಿ. ತಡೆಗೋಡೆಯನ್ನು ರಸ್ತೆ ಮಟ್ಟದಿಂದ ಮೇಲ್ಭಾಗಕ್ಕೆ 1.20 ಮೀ ಎತ್ತಿಸಲಾಗಿದೆ. ಸಾರ್ವಜನಿಕರ ಸುರಕ್ಷತೆಯನ್ನು ಕಾಪಾಡಲಾಗಿರುತ್ತದೆ. ಮೇಳನೀರುಗಾಲುವೆಯನ್ನು ಚೈನ್ ಅಂಕ್ನಿಂದ ಕವರ್ ಮಾಡಲಾಗಿರುತ್ತದೆ ಎಂಬ ಅಂಶವನ್ನು ಅವಗಾಹನೆಗೆ ತರಲಾಗಿದೆ".


The report shows that U-shaped storm water drain wall has been constructed. In the light of what is stated above the grievance with regard to Kasthurinagar is required to be closed on the ground that the grievance has been redressed.

However, larger issue with regard to cutting of the roads, pot holes etc., requires to be examined as directed

by me in my order dated;16.02.2018, the Zonal Chief Engineer is directed to submit the status report as stated above by the next date of hearing.

List this matter on 05.12.2018 at 3:00 P.M.

Communicate this order to the parties concerned along with Zonal Chief Engineer, BBMP, Bengaluru.


(Justice P. Vishwanatha Shetty), 23/8/2018
Lokayukta,
State of Karnataka.

*GAK

12) 05/12/2018.

ನೌ. ಲೋಕಾಯುಕ್ತೆ -
-ರವರ ಆದೇಶದಂತೆ
ಎದುರುದಾರರಿಗೆ ನೋಟಿಸ್
ಜಾರಿ ಮಾಡಿದ್ದು, ಸ್ವೀಕೃತಿ
ಮಾಡಿಸಿದೆ.
ಎದುರುದಾರರಿಂದ ಅನುಪಾಲನಾ
ವರದಿ ಬಂದಿರುವುದಿಲ್ಲ.

ARE-1.

16

KARNATAKA LOKAYUKTA, BENGALURU

No. Compt/Lok/BCD-12/2018

Date: 05.12.2018

ORDER

In my earlier order dated 23-08-2018, while closing this matter, I made an order which reads as hereunder;

"The report shows that U-shaped storm water drain wall has been constructed. In the light of what is stated above the grievance with regard to Kasthurinagar is required to be closed on the ground that the grievance has been redressed.

However, larger issue with regard to cutting of the roads, pot holes etc., requires to be examined as directed by me in my order dated;16.02.2018, the Zonal Chief Engineer is directed to submit the status report as stated above by the next date of hearing".


The matter is directed to be listed today for the purpose of filing the status report.




None of the Zonal Chief Engineers have filed the status report. Having regard to the facts and circumstances of the case another **eight (8) weeks time is given to the Zonal Chief Engineers to examine the matter and to file the status report with regard to the steps taken by them as per the directions issued by me in my order dated; 16.02.2018.**

Communicate this order to all the Zonal Chief Engineers of BBMP.

List this matter on 14.02.2019 at 3:00 P.M.


(Justice P. Vishwanatha Shetty), 5/14/2017
Lokayukta,
State of Karnataka.

*GAK

Heinkel Lokayukta
will be on official tour
on 14-2-19. Hence,
as directed by his lordship
the case shall be
adjudged to 26-2-19
( Heinkel Lokayukta)